
CRANK DIAGRAM

FOR MECHANICAL TOY

CRANK HANDLE



X = CENTER OF CRANK ARMS

** Please bend as accurately as possible.

